









DATA PENDUKUNG/LAMPIRAN SIMPEL PPU Foto Cerobong dan Sarana Sampling


Nama perusahaan :
 Kode cerobong :
 Koordinat cerobong :
 Sumber emisi :

No.	Ketentuan Teknis	Dokumentasi/Foto
1.	Cerobong emisi	Lubang sampling 
2.		Pagar pengaman dan tangga 
3.		Lantai kerja 
4.		Kode dan koordinat 

No.	Ketentuan Teknis	Dokumentasi/Foto
5.	Sumber listrik	
Khusus industri wajib CEMS		
1.	Sensor/probe	

No.	Ketentuan Teknis	Dokumentasi/Foto
2.	Gas standard	 <p>The top photograph shows a collection of gas cylinders of various colors (green, black, pink) arranged on a shelf. Some cylinders have labels, including one that says 'NITROGEN'. The bottom photograph is a close-up of a silver gas cylinder with a pressure gauge and regulator assembly. The label on the cylinder reads 'INTERNATIONAL INTERNATIONAL', 'UNI 1956 Compressed Gas, N.O.S. (Hydrogen, Carbon Dioxide)', '2.2', and 'Quantity: 4.72 kg'. A hand is visible near the bottom right of the cylinder.</p>

No.	Ketentuan Teknis	Dokumentasi/Foto
3.	Analyzer	 <p>The top photograph shows the interior of a rack-mounted electrical cabinet. It contains several modules, including a power supply unit at the top, a central control module with a small display, and various wiring and connectors. The bottom photograph shows the external view of the system. On the left is a glass-enclosed unit labeled '32-HNE03-GH001 SO2/NO/CO/CO2 ANALYZER PANEL'. On the right is a larger grey cabinet labeled '32-HNE03-GK001 PLC SYSTEM PANEL' which features a small screen and a row of red indicator lights.</p>

No.	Ketentuan Teknis	Dokumentasi/Foto
4.	Shelter	 A photograph showing the exterior of a white, rectangular shelter. A sign on the left side of the shelter reads "Continuous Emission Monitoring System (CEMS)". The shelter is situated outdoors under a blue metal structure, possibly part of an industrial facility. The ground is paved, and there are some shadows cast on it.
5.	Pendingin ruangan (AC) shelter	 A photograph showing the interior of the shelter. A white air conditioning unit is mounted on the wall. To the right, there is a control panel with a digital display showing "18.36". The interior is well-lit, and the walls are white.